



HI 200DNWM WEIGH MODULE
Series B

OPERATION AND INSTALLATION
MANUAL



Corporate Headquarters
9440 Carroll Park Drive, Suite 150
San Diego, CA 92121
Phone: (858) 278-2900
FAX: (858) 278-6700
Web-Site: <http://www.hardyinst.com>

Hardy Instruments Document Number: 0596-0227-01 Rev F
Copyright August 1998 Hardy Instruments, Inc. All Rights Reserved. Printed in the U.S.A. (941028)



Local Field Service

Hardy has over 200 field technicians in the U.S., and more positioned throughout the world to assist you in your support needs. We also have factory engineers who will travel to your facility anywhere in the world to help you solve challenging applications. We're ready to support you with:

- **Installation and start-up**
- **Routine maintenance and certification**
- **Plant audits and performance measurement**
- **Emergency troubleshooting and repair**

To request Emergency Service and Troubleshooting, Start-up, Installation, Calibration, Verification or to discuss a Maintenance Agreement please call **800-821-5831 Ext. 1757** or Emergency Service after hours (Standard Hours 6:00 AM to 6:00 PM Pacific Standard Time) and weekends Ext. 1111.

Outside the U.S

Hardy Instruments has built a network of support throughout the globe. For specific field service options available in your area please contact your local sales agent or our U.S. factory at **+1 858-292-2710, Ext. 1757**.

Table of Contents

TABLE OF CONTENTS	- I
TABLE OF ILLUSTRATIONS	- I
CHAPTER 1 - OVERVIEW	-1-1
Scope	-1-1
About Hardy Manuals	-1-1
Description	-1-2
WAVERSAVER®	-1-3
C2® Calibration	-1-4
The Button	-1-4
What is DeviceNet®?	-1-4
Physical Layer (Network Topology)	-1-5
CHAPTER 2 - SPECIFICATIONS	-2-1
SCOPE	-2-1
Conversion Rate	-2-1
Resolution	-2-1
Excitation Voltage	-2-1
Averages	-2-1
Load Sensors	-2-1
Non-Linearity	-2-1
Isolation	-2-1
Voltage	-2-1
Temperature Coefficient	-2-2
Temperature Range	-2-2
Temperature Storage Range	-2-2
Physical Dimensions	-2-2
Mounting Config	-2-2
Approvals	-2-2
Display	-2-2
DeviceNet	-2-2
Inputs	-2-2
Outputs	-2-2
Connectors	-2-3
J1	-2-3
J2	-2-3
J3	-2-3
Current Draw at 24VDC	-2-4

HI 200DNWM MANUAL

CHAPTER 3 - INSTALLATION	-3-1
SCOPE	-3-1
Unpacking	-3-1
Mechanical Installation	-3-3
Installing the Bare Weigh Module in an Enclosure	-3-3
Installing Weigh Module in DIN Rail	-3-5
Installing the Pre-stacked Weigh Module	-3-9
Electrical Installation	-3-10
Wiring Diagram for the J1 Load Sensor 8 Pin Connector	-3-10
Wiring Diagram for the J2 DeviceNet Interface 5 Pin Open	-3-11
Wiring Diagram for the J3 Set Point Out 4 Pin	-3-11
Wiring Diagram for the HI 215JB Junction Box	-3-11
C2 Loadcell Cable Connection (J1)	-3-11
Non-C2 Loadcell Cable Connection (J1)	-3-13
CHAPTER 4 - CONFIGURATION	-4-1
SCOPE	-4-1
Differences in the Series A and Series B Modules	-4-1
Changing from the Series A to the Series B Module	-4-1
Changing from the Series B to the Series A Module	-4-1
DIP Switch (S1) Configuration	-4-2
DIP Switch Location	-4-2
Configuring the Baud Rate	-4-2
Configuring the DeviceNet Node Address	-4-3
CHAPTER 5 - SETUP	-5-1
SCOPE	-5-1
Saving to Non-Volatile Ram	-5-1
Parameters	-5-2
Command Interface	-5-7
Format of Commands (4 byte input data)	-5-8
Examples Using the Command Interface	-5-9
Setpoints	-5-10
About SetPoints	-5-10
Dead Band Limits	-5-10
Three General Rules for Set Points	-5-11
Preact Limits	-5-11
Entering Set Points	-5-11
Setpoint Mode Parameters	-5-12
About Setpoint Mode Parameter	-5-12
Entering Setpoint Mode Parameters	-5-12

Table of Contents

CHAPTER 6 - CALIBRATION	-6-1
SCOPE	-6-1
Pre-Calibration Procedures	-6-1
C2® Calibration (The Button)	-6-1
C2® Calibration from RS NetWorx®	-6-2
Test Weight Calibration from RS NetWorx®	-6-3
CHAPTER 7 - OPERATION	-7-1
SCOPE	-7-1
Operating Capabilities	-7-1
Explicit Message Request Parameters	-7-1
Monitoring Weight Readings from RS NetWorx	-7-2
Network Status (DS1)	-7-2
Module Status (DS2)	-7-3
CHAPTER 8 - TROUBLESHOOTING	-8-1
SCOPE	-8-1
Module LED does not Come Back on When Performing	
Calibration with The Button	-8-1
Module LED is Flashing Red	-8-1
Mechanical Inspection	-8-1
Load Sharing and Load Sensor Checkout	-8-3
Guidelines for Instabilities on Formerly Operating Systems	-8-4
Electrical	8-5
Mechanical Stability and Configuration Settings	-8-6
INDEX	

HI 200DNWM MANUAL

CHAPTER 1 - OVERVIEW

Scope

This manual provides the user with a description of the operating procedures, specifications, installation and setup for the Hardy Instruments HI 200DNWM (**Hardy Instruments Series 200 DeviceNet™ Weigh Module**). To get the maximum service life from the HI 200DNWM users should use the instrument in accordance with the recommended practices implied or contained in this manual. The user should read and understand all cautions, warnings, and safety procedures referenced or explicitly stated in the manual, to ensure the safe operation of this product. Hardy Instruments appreciates your business. Should you experience any problems, please contact our Customer Support Department at:

Phone: (858) 278-2900

FAX: (858) 278-6700

Web Site: hardyinst.com

e-mail: support@hardyinst.com

NOTE:

DeviceNet is a trademark of the Open DeviceNet Vendor Association, Inc.

About Hardy Manuals

Every Hardy Installation and Operation manual is organized into easily referenced chapters, that are almost always the same:

- **Chapter One** - Provides an introduction and an **Overview** of the instrument and its capabilities.

- **Chapter Two** - Provides a complete list of **Specifications**.
- **Chapter Three** - Contains information needed to **Install** the HI 200DNWM weigh module.
- **Chapter Four** - Provides complete hardware **Configuration** instructions for setting dip switches and jumpers.
- **Chapter Five** - Pertains to the firmware **Setup** and preparation procedures to calibrate and operate the module.
- **Chapter Six** - Provides **Calibration** instructions.
- **Chapter Seven** - Pertains to the **Operation** of the HI 200DNWM weigh module.
- **Chapter Eight** - Pertains to the **Troubleshooting** procedures to repair the module.

Description

The Hardy Instruments HI 200DNWM is a small weigh module that communicates Net and Gross weights to other devices connected to a DeviceNet™ Network. The weigh module supports Hardy's C2® calibration and has four levels of WEVERSAVER®. The weigh module consists of a printed circuit card with standoffs (for mounting in an enclosure) or rails for DIN rail mounting. The weigh module outputs (produces) Gross, Net and Tare weights and inputs (consumes) Zero and Tare commands via DeviceNet™. Configuration includes:

1. Metric Poll
2. Averages (1-255)
3. WEVERSAVER[®]
4. Calibration Type (C2[®] or Hard Calibration) - Not configurable, Read Only
5. Span Weight
6. Set Point Values
 - a. Mode
 - b. Preact
 - c. Deadband

NOTE:

WEVERSAVER[®] and C2[®] are registered trademarks of Hardy Instruments, Inc.

Configuration data is stored in an EEPROM. I/O slave messaging is polled. The weight module supports two TTL levels out to relays for use as set points. A bit is supplied when the set point is reached.

NOTE:

Hardy Instruments does not supply the set point module.

WEVERSAVER[®]

Typically, mechanical noise is present in forces larger than the weight forces trying to be detected. The HI 200DNWM weigh module is fitted with WEVERSAVER[®] technology which eliminates the effects of vibratory forces present in all industrial weight control and measurement applications. By eliminating the factor of vibratory forces the controller is capable of identifying the actual weight data. WEVERSAVER[®] enables

the weigh module to distinguish between actual weight data and mechanical noise, both of which are typically transferred to the weight controller by the load cell signal. WAVERSAVER[®] can be configured from devicenet controller to ignore noise with frequencies as low as 0.5 Hz. One of three other additional cut off frequencies may be selected to provide a faster instrument response time. The default factory configuration is 1.0 Hz vibration frequency immunity.

C2[®] Calibration

C2[®] Second Generation Calibration enables a scale system to be calibrated electronically without using certified test weights which equals the systems load capacity. All Hardy Instruments C2[®] certified load sensors contain digital information detailing its unique performance characteristics. C2[®] Calibration is performed over the network or by simply pushing “**THE BUTTON**” and hold until the module status LED (DS2) goes out.

The Button

With one push of “**THE BUTTON**” the HI 200DNWM automatically electronically calibrates the weighing system with C2[®] certified load sensors, making the system ready for use. This saves system start up time costs and aggravations.

What is DeviceNet[®]?

The DeviceNet network is an open, global industry-standard communication network designed to provide an interface

through a single cable from a programmable controller directly to smart devices such as sensors, push buttons, motor starters, simple operator interfaces, drives and weigh modules. You no longer have to hard-wire each device to an I/O module or I/O block. Because you use significantly less wire, you spend far less time and money on wiring and installation time. The network also provides access to the intelligence present in the devices for superior diagnostics and troubleshooting to help increase system up time. The DeviceNet network lets you monitor your plant-floor devices from a central location and reconfigure them as your needs change or service them as required. You can, for example, configure the weigh module for different applications. The DeviceNet network's capabilities help ease integration, and reduce installation and wiring costs. (See Fig. 1-1)

Physical Layer (Network Topology)

- Trunk Line (thick or thin cable can be used)
- 120 ohm terminator at each end.
- Drop lines can extend to a maximum length of 20' feet.
- Drops may be daisy chained to multiple nodes.

- Zero length drops allow direct connection of nodes to the trunk.
- Multiple power supplies can be used for load distribution and backup.




FIG. 1-1 DEVICENET NETWORK

CHAPTER 2 - SPECIFICATIONS

SCOPE	Chapter 2 lists the specifications of the HI 200DNWM weigh module. Specifications are listed for the standard module and optional equipment. The specifications listed are designed to assist in the installation, operation and troubleshooting of the module. All service personnel should be familiar with this chapter before attempting an installation or repair of the instrument.
Conversion Rate	10 updates per second (When WAVER-SAVER is turned OFF or set to 1= 55 updates per second)
Resolution	20 bits
Excitation Voltage	0-5 VDC
Averages	1 to 255 User Selectable in Single Increments.
Load Sensors	Up to eight (8) 350 ohm Full Wheatstone Bridge, Strain Gauge Load Sensors/Cells (5 volt excitation) on one vessel. Using more than 4 load cells requires an external power supply.
Non-Linearity	0.0015% of Full Scale
Isolation	Non Isolated, uses external solid state relays for set points.
Voltage	Input power - Power from DeviceNet Cable <ul style="list-style-type: none">• 24 VDC +/- 1% Network• 11-25 VDC Node

HI 200 DNWM MANUAL

Temperature Coefficient	Less than 0.0005% per degree C for zero and span.
Temperature Range	-10 degrees C to +50 degrees C
Temperature Storage Range	-20 degrees to +85 degrees C
Physical Dimensions	3.80" W x 8.5" L x 1.0" H (96.52 mm W x 215.9 mm L x 25.4 mm H)
Mounting Config	<ul style="list-style-type: none">• DIN - Rail• Enclosure Mounting, pc board mounted to enclosure backplate.
Approvals	ODVA Conformance Tested
Display	None
DeviceNet	Type: Vendor Specific I/O Slave Messaging: Polling Profile: Refer to EDS Baud Rates: 125K, 250K, 500K
Inputs	4 bytes polled in
Outputs	4 bytes polled out

NOTE: *The Metric Poll parameter specifies the default format of the 4 bytes of output data from the weight scale. A zero value specifies that the default format is a 32 byte integer value containing net weight in pounds, with 3 decimal places. A one value specifies that the default format is a 32 byte integer value containing net weight in kilograms, with 3 decimal places.*

Connectors

Phoenix Combicon type with unsealed screw terminal mate. PC board side-vertical pins. All connector numbering is from left to right when looking down on the board with the connector side of the board facing toward you.

J1

Load Sensor 8 Pin

- 8 + EXC (Plus Excitation) + 5VDC
- 7 + SEN (Plus Sense)
- 6 + SIG (Plus Signal)
- 5 - SIG (Minus Signal)
- 4 - SEN (Minus Sense)
- 3 - EXC (Minus Excitation)
- 2 + C2
- 1 - C2

J2

DeviceNet Interface 5 pin Open

- 1 V - (Black)
- 2 CAN- (Blue)
- 3 SHIELD (Bare)
- 4 CAN+ (White)
- 5 V+ (Red)

J3

Set Point Out Interface 4 Pin

- 1 RLY 1 (Set Point Output One)
- 2 GND (Ground)
- 3 RLY 2 (Set Point Output Two)
- 4 +5 VDC

**Current Draw at
24VDC**

Table 1: Current Draw at 24 VDC

# Load Cells	Milli-Amp Reading	
	W/Relay TTL	W/O Relay TTL
1	167 ma	166 ma
2	174 ma	171 ma
3	179 ma	175 ma
4	189 ma	179 ma

CHAPTER 3 - INSTALLATION

SCOPE

Chapter 3 covers unpacking, cabling, inter-connecting and installing the HI 200DNWM weigh module. Users and service personnel should be familiar with the procedures in this chapter before installing or operating the weigh module.

Unpacking

1. Before signing the packing slip, inspect the packing for damage of any kind.
2. Report any damage to the carrier company immediately.
3. Check to see that everything in the package matches the bill of lading. You should normally have.
4. HI 200DNWM Module
 - 1 HI 200DNWM module with mating connectors
 - 1 Installation and Operation Manual

NOTE:

Electronic Data Sheet Software is available on our Website www.hardyinst.com

5. HI 200DNWM-DR Module with DIN Rail Kit
 - 1 HI 200DNWM module with mating connectors and a DIN Rail adapter.
 - 1 Installation and Operation Manual

NOTE:

Electronic Data Sheet Software is available on our Website www.hardyinst.com

6. HI 200DNWM-SK1 Modules (2 complete modules pre-stacked)

2 HI 200DNWM complete weigh modules pre-stacked.

1 Installation and Operation Manual

NOTE:

Electronic Data Sheet Software available on our Website www.hardyinst.com

7. HI 200DNWM Module with Stacking Kit (-SK)

1 HI 200DNWM Module with mating connectors

4 Standoffs

4 Phillips Pan Head Machine Screws

1 Installation and Operation Manual

NOTE:

Electronic Data Sheet Software is available on our Website www.hardyinst.com

8. HI 200DNWM Module Junction Box (-SS - Stainless Steel) or (-PS - Painted Steel)

1 HI 200DNWM Module with mating connectors mounted in either a stainless steel or painted steel NEMA 4/4X enclosure.

1 Summing Card mounted in either a stainless steel or painted steel NEMA 4/4X enclosure.

1 Installation and Operation Manual

NOTE:

Electronic Data Sheet Software is available on our Website www.hardyinst.com

9. If any items are missing, damaged, or there are any questions, please contact Hardy Customer Support at:

Hardy Instruments Inc.
3860 Calle Fortunada
San Diego, CA 92123-1825

Phone: (858) 278-4900

FAX: (858) 278-6700

Web Site: <http://www.hardyinst.com>

E-Mail:

hardysupport@hardyinst.com

10. Record the model number and serial number of the Weigh Module. Store this information in a convenient, secure location for reference when contacting Hardy Instruments Customer Support Department or to buy parts or firmware upgrades.

Mechanical Installation

Installing the Bare Weigh Module in an Enclosure

- Step 1. Make sure that the Weigh Module has at least 2 inches clearance around the entire weigh module. (See Fig. 3-1)
- Step 2. Drill four thru holes or threaded holes for four 6-32 pan head machine screws. (See Fig. 3-2)
- Step 3. Mount the four standoffs into the back panel. (See Fig. 3-3)
- Step 4. Fasten the weigh module to the standoffs by installing the four (4) pan head screws. (See Fig. 3-3)

Step 5. Connect the phoenix connectors to the headers mounted on the weigh module.

NOTE:

Stand offs and fasteners are not included.

NOTE:

Make sure that the connectors are seated properly in the headers.




FIG. 3-1 2" CLEARANCE AROUND THE MODULE




FIG. 3-2 HOLE DIAGRAM




FIG. 3-3 FASTENING MODULE TO BACK PLATE

Installing Weigh Module in DIN Rail

- Step 1. Take one end piece and one rail insert. Snap the rail guide insert into the end piece. Take the other end piece and install the other rail guide insert (See Fig. 3-4 & 3-5)
- Step 2. Take one of the small rail pieces and insert the rail pins into the end piece. (See Fig. 3-6)
- Step 3. Take one of the large rail pieces and insert the rail pins into the small rail piece. Do this on both sides. (See Fig. 3-6)
- Step 4. Continue installing the rail pieces until all rail pieces are installed. (See Fig. 3-7)




FIG. 3-4 INSTALLING THE RAIL GUIDE INSERT INTO THE END PIECE




FIG. 3-5 RAIL GUIDE INSERT IN THE END PIECE




FIG. 3-6 INSTALLATION OF THE RAIL PIECES

- Step 5. Gently slide the HI 200DNWM into the assembled DIN Rail until the board is flush against the other end piece. (See Fig. 3-7)
- Step 6. Take the other assembled end piece and snap it into the rail pieces. (See Fig. 3-7)
- Step 7. The HI 200DNWM is completely in the Din Rail assembly ready for installation. (See Fig. 3-8)




FIG. 3-7 INSTALLING THE WEIGH MODULE INTO THE ASSEMBLED DIN RAIL




FIG. 3-8 WEIGH MODULE INSTALLED IN THE DIN RAIL

NOTE:

The Weigh Module can be installed in the DIN Rail Assembly in either direction.

Installing the Pre-stacked Weigh Module

- Step 1. Drill four (4) thru holes or threaded holes for four (4) 6-32 threaded male 1/4" hex standoffs.
- Step 2. Screw four (4) 3/8" long x 1/4" wide male standoffs into the back panel.

NOTE:

The four (4) 3/8" x 1/4" do not come with the stacking kit.

NOTE:

Refer to Paragraph 3.1.1 for clearance and hole diameter specifications.

- Step 3. Place the bottom weigh module onto the 3/8" standoffs.
- Step 4. Fasten the 1.25" x 1/4" threaded female standoffs that come in the stacking kit to the 3/8" standoffs.
- Step 5. Place the second weigh module over the 1.25" standoffs aligning the holes with the threaded holes in the standoffs.
- Step 6. Place the four (4) #6 flat washers over the mounting holes on the second weigh module.
- Step 7. Place the four (4) #6 lock washers over the four (4) flat washers.
- Step 8. Screw the four (4) pan-head machine screws into the previously mounted standoffs until the upper weigh module is fastened securely to standoffs. (See Fig. 3-9)




FIG. 3-9 INSTALLING THE STACKING KIT

Electrical Installation

Wiring Diagram for the J1 Load Sensor 8 Pin Connector

<u>Pin</u>	<u>Description</u>
1	-C2
2	+C2
3	-EXC (Minus Excitation)
4	-SEN (Minus Sense)
5	-SIG (Minus Signal)
6	+SIG (Plus Signal)
7	+SEN (Plus Sense)
8	+EXC (Plus Excitation) +5VDC

NOTE:

If the sense lines are not used to measure the actual excitation voltage at the junction box, an error is introduced. The error is equal to the percentage of excitation voltage lost between the instrument and the junction box. If the excitation voltage at the back of

the instrument is 5 volts and the excitation voltage at the junction box was 4.9 volts, 0.1 volts was lost due to cable resistance. This loss will cause a linear error of 1% of applied load in all weight readings. This error is introduced because the programmed millivolt per volt data of the load point is multiplied by the voltage between the sense lines to compute the calibrations curve of the load point. (See Chapter 7, Paragraph 7.3.2, page 7-3)

Wiring Diagram for the J2 DeviceNet Interface 5 Pin Open

<u>Pin</u>	<u>Description</u>
1	V- (Black)
2	CAN- (Blue)
3	Shield (Bare)
4	CAN+ (White)
5	V+ (Red)

NOTE:

All power for the Weigh Module is received through the DeviceNet cable. A separate power supply is not required.

Wiring Diagram for the J3 Set Point Out 4 Pin

<u>Pin</u>	<u>Description</u>
1	RLY1 (Set Point Output One)
2	GND
3	RLY2 (Set Point Output Two)
4	+5 VDC

Wiring Diagram for the HI 215JB Junction Box

C2 Loadcell Cable Connection (J1)

When connecting the HI 215JB Junction box using C2 loadcell/point cable (6020-0001) use the following color code:

Model	EXC +	SEN +	SIG +	SIG -	SEN -	EXC -	C2 +	C2 -
J-BOX	RED	BLUE	GRN	WHT	BRWN	BLK	GREY	VIO

Table 1: C2 CABLE COLOR CODE/HI 215JB J-BOX




FIG. 3-10 C2 LOAD CELL CONNECTION/HI 215JB JUNCTION BOX

- 1 Recommended load cell cable, Hardy Instruments (Prt. #6020-0001)
- 2 Attach the load shield to the terminal block mounted next to the J1 connector on the HI 200DNWM Module.
- 3 Do not run load cell cable in parallel with or in the same conduit with power wiring, relay cables or any other high energy cables.
- 4 Remove the factory-installed jumpers for C2 wire load cell connection.
- 5 JB summing Card (Part. #0535-0465-05)

Non-C2 Loadcell Cable Connection (J1)

- 1 Attach the load cell cable to the terminal block mounted next to the J1 connector on the HI 200DNWM Module.
- 2 Factory installed jumpers to remain in place for 4 wire, non-C2 load cell connections. (See Fig. 3-11)
- 3 Do not run load cell cable in parallel with or in the same conduit with power wiring, relay cables or any other high energy cables.




FIG. 3-11 NON C2 LOAD CELL CONNECTION/HI 215JB JUNCTION BOX

CHAPTER 4 - CONFIGURATION

SCOPE

Chapter Four consists of all the procedures for configuring the HI 200DNWM Weigh Module. System configuration includes only hardware adjustments such as Jumper and Dip Switch settings. We recommend that maintenance personnel be familiar with this chapter before configuring the Weigh Module. Alternative configuration procedures are not recommended.

Differences in the Series A and Series B Modules

The Series B 200 DNWM module uses 4 bytes of input polled data. This requires each module to use a different .EDS file.

Changing from the Series A to the Series B Module

Configuration when using RS NetWorx for DeviceNet require the new .EDS file. This adds the 4 bytes of input polled data. If you want to use the new features of the module, the 4 bytes of input polled data need to be mapped into the scanner's scanlist.

If you do not map the input polled data into the scanner's scanlist, the module will operate as if it were a Series A. No changes need to be made to any ladder logic written for the module.

Changing from the Series B to the Series A Module

If you change from Series B to the older module, the configuration when using RS NetWorx for DeviceNet needs to be done using the older .EDS file. This will remove the 4 bytes of input polled data. These 4 bytes of data must then be removed from the scanner's scanlist. All

ladder logic written that refers to the 4 bytes of input polled data needs to be changed and any reference to the output data also needs to be reviewed and possible modified.

DIP Switch (S1) Configuration

Configuring the DIP switch sets the following:

1. Baud Rate
2. Node Address

DIP Switch Location

The DIP Switch is located between THE BUTTON and the J3 Header. (See Fig. 4-1 & 4-2)

Configuring the Baud Rate

Refer to Table 4-1 to configure the baud rate. 0 = OFF, 1 = ON (* is the default setting)

Baud Rate	S1-7	S1-8
125 kbps*	OFF	OFF
250 kbps	OFF	ON
500 kbps	ON	OFF
500 kbps	ON	ON

Table 4-1: Baud Rate





FIG. 4-1 S1 DIP SWITCH LOCATION

ON



OFF

FIG. 4-2 FACTORY DEFAULT DIP SWITCH CONFIGURATION

Configuring the DeviceNet Node Address

Refer to Table 4-2 to configure the DeviceNet Node Address.

Address	S1-1	S1-2	S1-3	S1-4	S1-5	S1-6
0	OFF	OFF	OFF	OFF	OFF	OFF
1	OFF	OFF	OFF	OFF	OFF	ON
2	OFF	OFF	OFF	OFF	ON	OFF
3	OFF	OFF	OFF	OFF	ON	ON
“	“	“	“	“	“	“
62	ON	ON	ON	ON	ON	OFF
63	ON	ON	ON	ON	ON	ON

Table 4-2: DeviceNet Node Addresses

CHAPTER 5 - SETUP

SCOPE

All information contained in Chapter 5 pertains to software or firmware settings or procedures to prepare the HI 200DNWM weigh module for calibration and operation. Alternatives to these procedures either explicit or implied, contained in this section are not recommended. It is very important that the user and service personnel be familiar with the procedures contained in this chapter, before going through the setup procedures.

Saving to Non-Volatile Ram

NOTE:

If you have an instrument with version 1.5, please refer to Devicenet Manual, REV B-6 or earlier for instructions about Saving to Non-Volatile Ram or contact Hardy Instruments Customer Service Department.

In version 2.1, the HI 200DNWM does not automatically save parameters to non-volatile memory. To save parameters to non-volatile RAM, set parameter 38 (Save non-volatile command) to 1.

This request should be sent after changing any configuration parameter. It does NOT need to be sent after altering a command parameters like TARE or ZERO. It does not need to be sent after doing a calibration. The necessary calibration data values are saved automatically. However, if you change parameters used during calibration, like “number of averages”, or “WAVER-

SAVER[®], for example, the SAVE request should be sent BEFORE cycling the power.

The non-volatile RAM has a maximum of 5,000,000 writes.

Parameters

- Parameter 1 = Metric Poll
True = kgs net False = lbs net
Length in Bytes = 1

NOTE:

Default settings are indicated by bold type.

- Parameter 2 = WAWERSAVER[®] Setting
0 = OFF 1 = 4 Hz, **2 = 2Hz**, 3 = 1.0 Hz, 4 = 1/2 Hz
Length in Bytes = 1

NOTE:

By selecting OFF (0) or 1 the module increases the updates per second from 10 to 55.

- Parameter 3 = Calibration Type
0 = Hard Cal, 1 = C2 Cal, Other = Not Cal'd (Read Only)
Length in Bytes = 1
- Parameter 4 = Span Weight in Lbs
1 to 2147483647 **10000.000**
Length in Bytes = 4
- Parameter 5 = Averages
0 to 255 **10**
Length in Bytes = 1
- Parameter 6 = Set Point One Mode
bit 7 = On/Off bit 1 = **Low/High**
bit 0 = **Net/Gross**
Length in Bytes = 1

- Parameter 7 = Set Point One Lbs Value
-2147483648 to 2147483647
10000.000
Length in Bytes = 4
- Parameter 8 = Set Point One Deadband
in Lbs
0 to 2147483647 **0.100**
Length in Bytes = 4
- Parameter 9 = Set Point One Preact in
Lbs
0.00 to 2147483.647
Length in Bytes = 4
- Parameter 10 = Set Point Two Type
bit 7 = **On/Off**
bit 1 = **Low/High**
bit 0 = **Net/Gross**
Length in Bytes = 1
- Parameter 11 = Set Point Two Lbs Value
-2147483648 to 2147483647
100000.000
Length in Bytes = 4
- Parameter 12 = Set Point Two Deadband
in Lbs
0 to 2147483.647 **0.100**
Length in Bytes = 4
- Parameter 13 = Set Point Two Preact in
Lbs
0 to 2147483647
Length in Bytes = 4

- Parameter 14 = Number of C2[®] Chips Found
0 to 8 (Read Only)
Length in Bytes = 1
- Parameter 15 = Net Weight in Lbs
Read Only
Length in Bytes = 4
- Parameter 16 = Gross Weight in Lbs
Read Only
Length in Bytes = 4
- Parameter 17 = Tare Weight in Lbs
-999999 - 999999 **0.00**
Length in Bytes = 4
- Parameter 18 = Tare Command
0 to 1 (Set to True to Complete Command)
Length in Bytes = 1
- Parameter 19 = Zero Command
0 to 1 (Set to True to Complete Command)
Length in Bytes = 1
- Parameter 20 = Calibrate Low Command
0 to 1 (Set to True to Complete Command)
Length in Bytes = 1
- Parameter 21 = Calibrate High Command
0 to 1 (Set to True to Complete Command)
Length in Bytes = 1

- Parameter 22 = Calibrate using C2[®]
0 to 1 (Set to True to Complete Command)
Length in Bytes = 1
- Parameter 23 = Span Weight in Kgs
0.000 to 2147483.647 **0.045**
Length in Bytes = 4
- Parameter 24 = Set Point One Kgs Value
Read Only
Length in Bytes = 4
- Parameter 25 = Set Point One Deadband
in Kgs
0.00 to 2147483.647 **0.045**
Length in Bytes = 4
- Parameter 26 = Set Point One Preact in
Kgs
0 to 2147483.647
Length in Bytes = 4
- Parameter 27 = Set Point Two Kgs Value
-2147483.648 to 2147483.647
4535.923
Length in Bytes = 4
- Parameter 28 = Set Point Two Deadband
in Kgs
0 to 2147483.647 **0.045**
Length in Bytes = 4
- Parameters 29 = Set Point Two Preact in
Kgs
0 to 2147483.647
Length in Bytes = 4

- Parameter 30 = Net Weight in Kgs
Read Only
Length in Bytes = 4
- Parameter 31 = Gross Weight in Kgs
Read Only
Length in Bytes = 4
- Parameter 32 = Tare Weight in Kgs
-999999 - 999999 **0.00**
Length in Bytes = 4
- Parameter 33 = Relay Outputs
Length in Bytes = 1
- Parameter 34 = A/D Counts
Length in Bytes = 4
- Parameter 35 = Calibration Low Weight
in Lbs.
Length in Bytes = 4
- Parameter 36 = Calibration Low Weight
in Kgs.
Length in Bytes = 4

The “Calibration Low Weight” parameter specifies the weight on the scale when the low step of a calibration is done in Traditional Calibration and is the Reference Point for C2 Calibration.

- Parameter 37 = Weight Multiplier
Length in Bytes = 4

This integer parameter can be set to 1, 10, 100, etc. to allow the user to select

the number of decimal places in the 32 bit integer weight outputs. The value 0 causes these weight outputs to be in floating point format.

NOTE:

This applies ONLY to the weights as viewed through the I/O (Command) interface. The explicit message interface continues to use 3 decimal place 32 bit integer format only.

- Parameter 38 = Write non-volatile command.
Length in Bytes = 1

Setting this parameter to 1 will cause a save to non-volatile memory. Calibration data is saved to non-volatile memory automatically. Other parameters must be saved using this command.

- Parameter 39 = Parameter high word.
Length in Bytes = 2
This parameter is used in the command interface as described below:

Command Interface

The Command Interface allows easy access to all parameters without using explicit messages.

The HI 200DNWM version 2.1 produces 4 bytes of polled output data and consumes 4 bytes of polled input data. The 4 bytes of input data can be used to set parameters in the module and to specify what data should be placed in the 4 bytes of output data.

Format of Commands (4 byte input data)

Byte 0	Parameter value, least significant byte. (Used by the WRITE command only.
Byte 1	Parameter value, second least significant byte. (Used by the WRITE command only.)
Byte 2	Parameter number. The parameter number is the instance of the parameter object. These are listed in the HI 200DNWM manual.
Byte 3	(Command byte): 0=READ command. 1 = WRITE command

Most of the HI 200DNWM's parameters are only 1 byte long, making it possible to write them with a single command. There are also some 4 byte parameters. To write one of them:

- Step 1. First write the 2 most significant bytes, using a WRITE command as described above, with 0x27 in the parameter number field.
- Step 2. Write the least significant bytes using normal parameter numbers. The module will combine the value written to parameter 0x27 with the least significant bytes to produce the value written to the 4 byte parameter.

The 4 bytes written to the output table are as follows:

- If the Command byte of the input data is 0 (READ), the data is the value of the specified parameter, least significant byte first.

- If the specified parameter is an invalid number (0 for example: there is no parameter number 0), the data is net weight, with units as determined by the METRIC POLL parameter.
- If the Command byte of the input data is non-zero (WRITE), the output data echoes the input data.

Examples Using the Command Interface

Reading Gross Weight in the polled output data.

1. First word (2 least significant bytes) of the input data is not used. Ignore.
2. Lower byte of second word is the parameter number. Gross weight in lbs is parameter #16.
3. Upper byte of second word set is “0” indicating read.

This causes the unit to output the Gross weight in lbs to the output polled data area. Resolution and data type would depend on the Weight Multiplier setting.

Writing new value to number of averages.

1. First byte of first word on the input data is the new valued wanted.
2. Upper byte of first word should be 0 and is not used.
3. Lower byte of second word is the parameter number. Averages is parameter #5.
4. Upper byte of second word is set to “1” to indicate write.

This causes the unit to write the value in the first byte of the first word to the Averages

parameter. During the execution of the command, the output polled data reflects the input polled data.

Setpoints

About Set-Points

The set point value is the target weight or level in either net or gross weight units

Dead Band Limits

The dead band value can be set as a High or Low value. It is used to deactivate the set point.

For example:

If a set point value was 1000 pounds and the dead band was set to 5 pounds, the relay would close at a 1000 pounds but not open until the weight dropped to 995 pounds. This is used if a set point is a **high** trip limit. A High dead band would be used for a low trip limit. Examples are show for Low and High Trip Limits in Fig. 5-2.




FIG. 5-1 LOW AND HIGH PRACT TRIP LIMITS

Three General Rules for Set Points

1. Set Points activate at the set point plus the preact.
2. Set Points deactivate at the set point plus the deadband.
3. The deadband should be numerically larger than the preact.

Preact Limits

1. The preact value is the number of units below or above the set point at which the relay will trip.
2. The preact value is used as an “in-flight” compensation value when filling a vessel. If set to zero, there will be no compensation.

Entering Set Points

Change the Set Point Parameters in accordance with the DeviceNet Manager you are

using. Be sure to read the DeviceNet Manager instructions first before setting.

Setpoint Mode Parameters

About Setpoint Mode Parameter

The Setpoint mode parameter is a bit encoded byte that affects the behavior of the setpoint.

Entering Setpoint Mode Parameters

Bit	Description
Bit 7	Setpoint On/Off. Set to 1 to activate the setpoint, set to 0 to disable it.
Bit 6	Set to 1 to output 0 volts (Force Relay Off)
Bit 5	Set to 1 to output 5 volts (Force Relay On)
Bit 1	Set to 0 for a gain in weight setpoint, set to 1 for a loss in weight setpoint.
Bit 0	Set to 1 for a setpoint based on Net weight, or to 0 for a setpoint based on gross weight.

CHAPTER 6 - CALIBRATION

SCOPE

Chapter 6 pertains to the calibration procedures for the HI 200DNWM weigh module. Alternatives to any procedures either implied or explicitly contained in this chapter are not recommended. In order for the weigh module to work properly, it must be calibrated prior to operation. All calibration should be recalibrated periodically, or when not in use for extended periods of time. Be sure to follow all the procedures completely to insure that the weights read by the module are accurate. It is very important that the user and service personnel be familiar with the procedures contained in this chapter, before installing or operating the HI 200DNWM weigh module.

Pre-Calibration Procedures

- Step 1. Check to see if the load cell/sensor/points are properly installed. Refer to your load cell I&M manual for proper installation instructions.
- Step 2. Check to be sure that the connectors are installed firmly in the weigh module headers.

NOTE:

You need to go through the pre-calibration procedures before each calibration, regardless of the type of calibration you are performing.

C2[®] Calibration (The Button)

- Step 1. The Module LED must be green in color. If it is not do not try to calibrate the instrument. Contact Hardy Instruments

Customer Support for assistance.

- Step 2. Press the RED BUTTON on the weigh module printed circuit board and hold the button down until the Module Status LED goes off. (See Fig. 6-1)

NOTE:

This could take up to 2 seconds.

- Step 3. When the Module Status LED comes back on. Release the RED BUTTON. The weigh module system is calibrated.
- Step 4. If the LED does not come back on contact Hardy Customer Support for assistance.




FIG. 6-1 THE RED BUTTON

C2[®] Calibration from RS NetWorx[®]

- Step 1. On the PC open RS NetWorx[®]
- Step 2. Browse the Network.
- Step 3. Double click on the Node Icon of the weigh module you want to calibrate. For example: Node

36. The DeviceNet Weigh Module Dialog Box appears.
- Step 4. Click on the Parameter tab. The Parameter List appears with the information for the weigh module at address 36.
- Step 5. Click on Cal LO.
- Step 6. Enter the Cal LO value.
- Step 7. Click on the Apply button.
- Step 8. Click on Yes.
- Step 9. Click on C2 Cal Cmd.
- Step 10. Set the C2 Cal Cmd to “1”.
- Step 11. Click on the Apply button.
- Step 12. Click on Yes.
- Step 13. Click on Cmd Save non-vol.
- Step 14. Set the Cmd Save non-vol to “1”.
- Step 15. Click on the Apply button.
- Step 16. Click on Yes.
- Step 17. The calibration is complete.

NOTE:

Requires C2[®] load sensors or load points.

NOTE:

RS NetWorx[®] is a registered trademark of Rockwell Automation.

Test Weight Calibration from RS NetWorx[®]

- Step 1. On the PC open RS NetWorx[®]
- Step 2. Browse the Network.
- Step 3. Double click on the Node Icon of the weigh module you want to calibrate. For example: Node 36. The DeviceNet Weigh Module Dialog Box appears.
- Step 4. Click on the Parameter tab. The Parameter List appears with the information for the weigh module at address 36.
- Step 5. Click on Span Weight.

- Step 6. Enter the Span Weight Value.
- Step 7. Click on Cal LO.
- Step 8. Enter the Cal LO weight.
- Step 9. Click on Cal LO command.
- Step 10. Set the Cal LO to "1".
- Step 11. Click on the Apply button.
- Step 12. Click on Yes.
- Step 13. Place the test weight on the scale.
- Step 14. Click on Cal HI command.
- Step 15. Set the Cal HI command to "1"
- Step 16. Click on the Apply button.
- Step 17. Click on Yes.
- Step 18. Click on Cmd Save non-vol.
- Step 19. Set the Cmd Save non-vol to "1".
- Step 20. Click on the Apply button.
- Step 21. Click on Yes.
- Step 22. The calibration is complete.

CHAPTER 7 - OPERATION

SCOPE

All information contained in Chapter 7 pertains to the operation of the HI 200DNWM weigh module. We recommend that the processes and procedures contained in this chapter be followed to insure that the module give the user maximum quality performance. It is very important that the user be familiar with this chapter before operating the weigh module.

Operating Capabilities

The HI 200DNWM can do the following or can be used in the following operations:

1. Monitor Weight Readings
2. Filling
3. Dispensing
4. Check Weighing
5. Batching

Explicit Message Request Parameters

The procedures for sending the Explicit Message Requests are unique to each PLC and the user needs to refer to their PLC users guide, PLC DeviceNet Scanner section for instructions. The HI 200DNWM needs the following information to respond to an Explicit Message Request:

- **SERVICE:** The HI200DNWM WEIGH MODULE can process the “Get_Attribute_Single” (14) and “Set_Attribute_Single” (16).
- **CLASS:** The Device Net parameter Class is 15.
- **INSTANCE:** The HI 200DNWM WEIGH MODULE parameter number

can be found in the HI 200DNWM WEIGH MODULE I&O manual.

- **ATTRIBUTE:** The parameter value attribute number is 1.
- **DATA:** (varies)

NOTE:

Data length can vary, be sure to enter the correct length (size) of data or problems will occur.

NOTE:

Order of bytes must be least significant first.

Monitoring Weight Readings from RS NetWorx

- Step 1. On the PC open RS NetWorx.
- Step 2. Browse the Network.
- Step 3. Double click on the Node Icon of the weigh module you want to monitor. For example: Node 36. The DeviceNet Weigh Module Dialog Box appears for Node 36.
- Step 4. Click on the Parameters Tab.
- Step 5. All the parameters including the weights are displayed.
- Step 6. The NET, GROSS, and TARE weights are now being monitored.

NOTE:

The HI 200DNWM can be used for Batching, Filling, Dispensing, and Check Weighing applications.

Network Status (DS1)

STATE	LED	INDICATION
NOT POWERED/ NOT ON LINE	OFF	DEVICE IS NOT ON LINE 1. NO POWER APPLIED 2. Dup_MAC_ID TEST NOT COMPLETE
OPERATIONAL AND ON-LINE	GREEN	ON LINE NORMAL CONDITION WITH CONNECTIONS ESTABLISHED.

Table 7-1: NETWORK STATUS (DS1)

STATE	LED	INDICATION
OPERATION AND ON LINE NOT CONNECTED	FLASHING GREEN	ON LINE NORMAL CONDITION NO CONNECTIONS Dup_MAC_ID PASSED & ON LINE, NO CONNECTIONS TO OTHER NODES.
CRITICAL FAULT OR LINK FAILURE	RED	UNRECOVERABLE FAULT (MAY NEED REPLACING) FAILED COMMUNICATIONS (DUPLICATE Mac ID OR BUS OFF)

Table 7-1: NETWORK STATUS (DS1)

Module Status (DS2)

STATE	LED	INDICATION
NOT POWERED/ NOT ON LINE	OFF	DEVICE IS NOT ON LINE 1. NO POWER APPLIED
OPERATIONAL	GREEN	NORMAL CONDITION
MINOR FAULT AND/OR CONNECTION TIME-OUT	FLASHING RED	RECOVERABLE FAULT A/D ERROR, USUALLY CAUSED BY BAD CONNECTION TO LOAD CELLS LOAD CELL OUT OF RANGE. SENSE LINES MUST BE INSTALLED. (See Chapter 3, Page 3-10 for more information)
CRITICAL FAULT OR LINK FAILURE	RED	UNRECOVERABLE FAULT (Board MAY NEED REPLACING) FAILURE IN A-D.

Table 7-2: MODULE STATUS (DS2)

CHAPTER 8 - TROUBLESHOOTING

SCOPE

All the information in Chapter 8 pertains to the troubleshooting and resolution of operating problems that may occur. All maintenance personnel and users should be familiar with Chapter 8 before attempting to repair the HI 200DNWM.

Module LED does not Come Back on When Performing Calibration with The Button

If the Module LED does not come back on when performing The Button (C2 Calibration) it indicates a hardware problem. Contact Hardy Customer Support for assistance.

Module LED is Flashing Red

Solution: Check all the connections to be sure they are securely fastened. Reinstall if any appear to be loose.

Mechanical Inspection

See Fig. 8-1




FIG. 8-1 MECHANICAL INSPECTION

Load Sharing and Load Sensor Checkout

See Figure 8-2




FIG. 8-2 LOAD SHARING AND LOAD SENSOR CHECKOUT

**Guidelines for
Instabilities on
Formerly Operat-
ing Systems**

See Figure 8-3




FIG. 8-3 GUIDELINES FOR INSTABILITIES ON FORMERLY OPERATING SYSTEMS

Electrical

See Figure 8-4




FIG. 8-4 GUIDELINES FOR INSTABILITIES ON FORMERLY OPERATING SYSTEMS - ELECTRICAL

Mechanical Stability and Configuration Settings

See Figure 8-5




FIG. 8-5 MECHANICAL STABILITY AND CONFIGURATION SETTINGS

Index

A

About Hardy Manuals 1-1
About Setpoint Mode Parameters 5-12
About SetPoints 5-10
Approvals 2-2
ATTRIBUTE 7-2
Averages 2-1

B

Batching 7-1
Baud Rate 4-2

C

C2 Loadcell Cable Connection 3-11
C2[®] Calibration 1-4
C2[®] Calibration (The Button) 6-1
C2[®] Calibration from a Personal Computer 6-2
C2[®] Second Generation Calibration 1-4
Calibration Type 1-3
Check Weighing 7-1
CLASS 7-1
Command Interface 5-7
Configuring the Baud Rate 4-2
Configuring the DeviceNet Node Address 4-3
Connectors 2-3
Conversion Rate 2-1
Current Draw at 24VDC 2-4
Customer Support Department 1-1

D

Daisy Chained 1-5
DATA 7-2
Deactivate the Set Point 5-10
Dead Band Limits 5-10
DeviceNet 2-2
DeviceNet Cable 2-1
DeviceNet Manager 6-2, 6-3
DeviceNet Node Address 4-3

DeviceNet™ Network 1-2
DeviceNet™. Configuration 1-2
DIN Rail Adapter 3-1
DIN Rail Kit 3-1
DIP Switch (S1) Configuration 4-2
DIP Switch Location 4-2
Dispensing 7-1
Display 2-2
Drop Lines 1-5
Drops 1-5

E

Electrica 8-5
Electrical Installation 3-10
Electronic Data Sheet Software 3-2
Entering Set Points 5-11
Entering Setpoint Mode Parameters 5-12
Excitation Voltage 2-1
Explicit Message Request Parameters 7-1

F

Filling 7-1
Format of Commands (4 byte input data) 5-8

G

Global Industry-Standard Communication Network 1-4
Guidelines for Instabilities on Formerly Operating Systems 8-4

H

HI 200DNWM Module Junction Box 3-2
HI 200DNWM Module with Stacking Kit 3-2
HI 200DNWM-SK1 Modules 3-2
High dead band 5-10
high trip limit 5-10

HI 200DNWM MANUAL

I

- I/O block 1-5
- I/O module 1-5
- Input power 2-1
- Inputs 2-2
- Installing the Bare Weigh Module in an Enclosure 3-3
- Installing the Pre-stacked Weigh Module 3-9
- Installing Weigh Module in DIN Rail 3-5
- INSTANCE 7-1

J

- J1 2-3
- J2 2-3
- J3 2-3

L

- load cell I&M manual 6-1
- Load Sensors 2-1
- Load Sharing and Load Sensor Check-out 8-3
- Low and High Trip Limits 5-10
- low trip limit 5-10

M

- Mechanical Installation 3-3
- Mechanical Stability and Configuration Settings 8-6
- Metric Poll 2-2
- Module LED does not Come Back on When Performing Calibration with The Button 8-1
- Module LED is Flashing Red 8-1
- Module Status (DS2) 7-3
- Module Status LED 6-2
- Monitor Weight Readings 7-1
- Monitoring Weight Readings 7-2
- Mounting Config 2-2
- Multiple power supplies 1-6

N

- Network Status (DS1) 7-2
- Node Icon 6-2, 6-3
- Non-C2 Loadcell Cable Connection (J1) 3-13
- Non-Linearity 2-1
- Non-Volatile RAM 5-1

O

- Operating Capabilities 7-1
- Outputs 2-2

P

- Parameters 5-2
- Phoenix Combicon 2-3
- Physical Dimensions 2-2
- Physical Layer 1-5
- Preact Limits 5-11
- Pre-Calibration Procedures 6-1

R

- Red Button 6-2
- Resolution 2-1

S

- Saving to Non-Volatile Ram 5-1
- Scale System 1-4
- Set Point Values 1-3
- Setpoint Mode Parameters 5-12
- Setpoints 5-10
- Six (6) Conductor Load Cell Cable 3-13
- Span Weight 1-3
- Standoffs 1-2

T

- Tare Weights 1-2
- Temperature Coefficient 2-2
- Temperature Range 2-2
- Temperature Storage Range 2-2
- Test Weight Calibration Procedures 6-3
- THE BUTTON 1-4, 4-2

The Button 1-4
Three General Rules for Set Points 5-11
Trunk Line 1-5

U

Unpacking 3-1
Unused Wires 3-14

V

Vendor Specific 2-2
Voltage 2-1

W

WAVERSAVER 1-3
Weigh Module 1-2
What is DeviceNet[®]? 1-4
Wiring Diagram for the HI 215JB Junction Box 3-11
Wiring Diagram for the J2 DeviceNet Interface 5 Pin Open 3-11
Wiring Diagram for the J3 Set Point Out 4 Pin 3-11

Z

Zero and Tare commands 1-2
Zero Length Drops 1-6