CERTIFICATE OF COMPLIANCE

Certificate Number 20120815-E233408

Report Reference E233408-20120419

Issue Date 2012-AUGUST-15

Issued to: HARDY PROCESS SOLUTIONS

SUITE 150

9440 CARROLL PARK DR SAN DIEGO CA 92121

This is to certify that representative samples of

PROCESS CONTROL EQUIPMENT, ELECTRICAL

See Addendum.

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: Standard for Electrical Equipment for Measurement,

Control, and Laboratory - Part 1: General Requirements, UL

61010-1.

Standard for Safety Requirements for Electrical Equipment for Measurement, Control, and Laboratory Use - Part 1: General Requirements, CSA C22.2 No 61010-1-04.

Additional Information: See the UL Online Certifications Directory at

www.ul.com/database for additional information

Only those products bearing the UL Listing Mark for the US and Canada should be considered as being covered by UL's Listing and Follow-Up Service meeting the appropriate requirements for US and Canada.

The UL Listing Mark for the US and Canada generally includes: the UL in a circle symbol with "C" and "US" identifiers: [©] the word "LISTED"; a control number (may be alphanumeric) assigned by UL; and the product category name (product identifier) as indicated in the appropriate UL Directory.

Look for the UL Listing Mark on the product.

William R. Carney, Director, North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at www.ul.com/contactus

(U)

CERTIFICATE OF COMPLIANCE

20120815-E233408 **Certificate Number** E233408-20120419 **Report Reference** 2012-AUGUST-15 **Issue Date**

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Weight Indicating Controller, Model HI 2151/30WC, may be followed by RM, BR, or WS, may be followed by A1, A2 or A3, may be followed by B1, B2, B5, B6, B7, B8, B9, B12 or B14, may be followed by C1, C2, or C6, may be followed by D1 or D2, may be followed by E2, may be followed by E3, E4, F1, F2, F3, F4, F5, F6, F7, F8 or F9.

Weight Indicator Model HI 2110WI, may be followed by RM, followed by AN, BCD, B6, B7, RIO, or PB, may be followed by 240.

William R. Carrey

William R. Carney, Director, North American Certification Programs

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, contact a local UL Customer Service Representative at www.ul.com/contactus

